
CITY OF BALTIMORE WET W SMOKE AND DYED W	Page 1 of 5		
Sewershed: Low Level Subsewershed: 41	Company: REI/DRAYCO	Date: 08/05/2008	
Test Type: Smoke	Ground Condition: Dry: X Damp: _ Wet: _	Supervisor: E.R. Crew: 04	
Manhole ID: S19I1_022MH	Test ID: 1029-514	Notifications Made:X_ Residents, Fire, 311	

Field Sketch: (Show all manholes with numbers, blower placement location, sandbag or isolation locations, street names, building addresses and locations, defect locations and photograph numbers)



	CITY OF BALTIMORE WET SMOKE AND DYED				EE		Page 2 of 5	
S	Sewershed: Low Level Subsewershed: 41	Con	npany: RE	I/DRAYC	0		Date: 08/05/2008	
	Test Type: Smoke		Ground Co			Su	upervisor: E.R. Crew: 04	
Ma	nhole ID: S19I1_022MH	Dry: X Damp:_ Wet:_ Test ID: 1029-514			-	Notifications Made:X Residents, Fire, 311		
Field SI	ketch: (Show all manholes with nu					olation location		ses
Defect		and locations, do			tograph n Draina	10		
No.	Address	Type	Location	Sector	Area	Severity	Photo Number	
1	2534 SOUTHDENE AVE.	02	07	02	5	03	1029-514_OB01-01.JP0	
2	2543 SOUTHDENE AVE.	02	07	02	6	03	1029-514_OB02-01.JP0	
3	2553 SOUTHDENE AVE.	02	07	02	6	03	1029-514_OB03-01.JP0	3
-					1			
								_
			 	<u> </u>	<u> </u>			\dashv
-			+	-	 			_
			†	 	 			
								\neg
		OI	SERVAT		DES			
	Source Type		Location			Sector	Severity	
	ain Sewer 10 MH Frame	01 Paved C		Non-Pay			01 No Smoke	
	ervice Line 11 Storm Drain	02 Asphalt		Field/Wo	ods 0	2 Private	02 Trace	
03 Cleanout 12 Catch Basin		03 Paved C		Alley Golf Cou	ırco		03 Moderate 04 Major	\dashv
04 Downspout 13 Storm MH 05 Area Drain 14 Storm Ditch		04 Drivewa 05 Sidewall		Other	1126		U4 IVIAJUI	_
	vy. Drain 15 Excavation	06 Curb	14	Outel				\dashv
	air. Drain 16 Water Line	07 Yard - F	ront				1	\dashv
	ound. Drai 17 Tele. Pole	08 Yard - B						
	dg. Interio 18 Other	09 Yard - S						

CITY OF BALTIMORE SMOKE TESTING OBSERVATION SUMMARY LOW LEVEL SEWERSHED

BALTIMORE CITY PROJECT 1029 REI/DRAYCO

Unique Test ID: 514 Date: 08/05/2008 Basin: LL - 41 Manhole ID: S19I1_022MH Defect No: OB01 Supervisor: E.R. Crew: 04 Dye Test Recommended: N

2534 SOUTHDENE AVE.

Source Type: 02 Service Line Location: 07 Yard - Front

Sector: 02 Private Severity: 03 Moderate Drainage Area: 5

Comments: SMOKE EMINATING FROM BELOW GRADE HOLE IN GROUND IN FRONT YARD.

SMOKE TEST PHOTOGRAPHS



Photograph No: OB01-01 Filename: 1029-514_OB01-01.jpg

CITY OF BALTIMORE SMOKE TESTING OBSERVATION SUMMARY LOW LEVEL SEWERSHED

BALTIMORE CITY PROJECT 1029 REI/DRAYCO

Unique Test ID: 514 Date: 08/05/2008 Basin: LL - 41 Manhole ID: S19I1_022MH Defect No: OB02 Supervisor: E.R. Crew: 04 Dye Test Recommended: N

2543 SOUTHDENE AVE.

Source Type: 02 Service Line Location: 07 Yard - Front

Sector: 02 Private Severity: 03 Moderate Drainage Area: 6

Comments: SMOKE EMINATING FROM BELOW GRADE HOLE IN GROUND IN FRONT YARD.

SMOKE TEST PHOTOGRAPHS



Photograph No: OB02-01 Filename: 1029-514_OB02-01.jpg

CITY OF BALTIMORE SMOKE TESTING OBSERVATION SUMMARY LOW LEVEL SEWERSHED

BALTIMORE CITY PROJECT 1029 REI/DRAYCO

Unique Test ID: 514 Date: 08/05/2008 Basin: LL - 41 Manhole ID: S19I1_022MH Defect No: OB03 Supervisor: E.R. Crew: 04 Dye Test Recommended: N

2553 SOUTHDENE AVE.

Source Type: 02 Service Line Location: 07 Yard - Front

Sector: 02 Private Severity: 03 Moderate Drainage Area: 6

Comments: SMOKE EMINATING FROM BELOW GRADE HOLE IN GROUND IN FRONT YARD.

SMOKE TEST PHOTOGRAPHS



Photograph No: OB03-01 Filename: 1029-514_OB03-01.jpg